

# Clear all Channels

Pretty straightforward, this one. C for clear:

```
C[cr]
```

Alternately, '0' in the G command as as channel number functions as all-call:

```
G0@X:0[cr] where X is [0 255]
```

```
G0@200:0[cr] set all to ~ 80%G0@0:0[cr] another way to clear all channels
```

---

Revision #1

Created Wed, Oct 30, 2019 6:13 PM by ESINC

Updated Wed, Oct 30, 2019 6:16 PM by ESINC